Pneumatic Control Valve

Features

- Converts vacuum signal into pneumatic signal
- Different vacuum ranges are set by adjusting the screws on the valve
- There are two different valves for option: normally open valve and normally closed valve



How to order

ZVAB - NC

① Series	② Function	Connection thread
ZVAB	NC - Normally closed	Default, G1/8 male thread
	NO - Normally open	

Technical parameters

	Model	Output function	Air supply pressure bar	Signal range -kPa	Hysteresis -kPa	Working temperature	Weight g	
ĺ	ZVAB-NC	NC	1.5~8	15~95	12	-10~60	44	
	ZVAB-NO	NO.	1 5-8	10-95	3	-10~60	44	

ZVA8

Symbol



ZVAB-NC ZVAB-NQ

Dimensions (mm)

